

	DESIG	CP	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
Ī	CHECK	(ED	APPROVED	DRAWING NO.	REV. A
ı		#	#	DSI 9324 SHEET	1 OF 1
Ì	DATE			TITLE	SCALE
	06.0	3.24		BOLT SUBSTITUTION	NTS
	Α		06.03.24	NEW ISSUE	

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS IIN-D412-702 REV. C

REF. CANADIAN STC: SH04-7 ISSUE 3 REF. FAA STC: SR01997NY

PURPOSE:

Variations in some aircraft, such as repairs or different insulation blankets, means that the MS24694-S152 screws used to attach the D3196-1/-3 bars are not always sufficiently long to properly secure the bars.

CHANGE:

For the D412-702-011/-013/-017/-021/-023/-027 kits, when installing D3196-1 or D3196-3 bars into the aircraft, it is acceptable to use longer MS24694-Sxxx screws instead of the MS24694-S152 screws called up in Installation Instructions IIN-D412-702.

MS24694-S154 screws have been added to kits for optional use as follows:

QTY	QTY	QTY	QTY	QTY	QTY		
-011	-013	-017	-021	-023	-027	P/N	Description
Х						D412-702-011	13-Man Shoulder Harness Kit
	X					D412-702-013	5-Man Shoulder Harness Kit
		Х				D412-702-017	4-Man Side Facing Shoulder Harness Kit
			Х			D412-702-021	13-Man Shoulder Harness Kit, 4-point
				Χ		D412-702-023	5-Man Shoulder Harness Kit 4-point
					Х	D412-702-027	4-Man Side Facing Shoulder Harness Kit, 4-point
8	2	6	8	2	6	MS24694-S154	Screw

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED

D. SHEPHERD (DE # 02)

DATE: 06.03.24
CERT. NO.: SH04-7
ISSUE NO.: 3